Figure 1. Overall view of the three samples containing spike tooth fracture areas. The numbers by the samples correspond to the parts list in the first portion of section B of this report.