Figure 11. Closer view of the spike tooth fracture area on the sample from piece CW106 of SWB#3, showing the mechanical damage associated with the spike tooth fracture area. (2X)



Figure 12. Samples cut from piece CW1006 (left) and piece CW1004 (right) of the rear spar. Fracture areas are toward the center of the page on each sample.