


**Cross-sectional view of  
compression damage**  
Note thinning of PTFE  
insulation. Thinned side  
is where impressions of  
wire strands could be  
seen on the surface in  
Figure 38.



Systems 9 - Exhibit No. 9B - Photo 39. Figure 39g. Lo-Z wire from N93105 (model no. FG420A13, serial no. A-16).